

DL32 trimless - Installation instruction




AC Input

C ut hole


Connect Wire






F ix the outer frame

B rush the ceiling





Paint the ceiling